



Overview of Robust Design, Propagation of Error and Tolerance Analysis

Pat Whitcomb, Founder Stat-Ease, Inc.

pat@statease.com

December 15, 2020

Making the most of this learning
opportunity



Hide the Control Panel

Mute your line



To prevent audio disruptions, all attendees will be muted.

Questions can be posted in the Question area. If they are not addressed during the webinar, I will reply via email afterwards.


Questions may also be sent to stathelp@statease.com. Please provide your company name and, if you are using Design-Expert, the serial number (found under Help, About).

Note: The slides and a recording of this webinar will be posted on the Webinars page of the Stat-Ease website within a few days.

Agenda Transition



- Robust Design Concepts
- Propagation of Error (POE)
- RSM Analysis with TA
 - Lathe Machined Parts
 - Tolerance analysis
 - Partitioning variation to inputs




Robust Design

3

Agenda Transition



- **Robust Design Concepts**
- Propagation of Error (POE)
- RSM Analysis with TA
 - Lathe Machined Parts
 - Tolerance analysis
 - Partitioning variation to inputs



Robust Design


4

Robust Design



Functional Design:

- Use DOE to model response **mean** as a function of controllable factor levels.
- Choose levels of controllable factors to achieve targeted values of the responses.



Robust Design


5

Robust Design



Robust Design:

- Use DOE to model response **variability** as a function of control and uncontrolled factor levels.
- Choose levels of control factors to reduce variation caused by:
 - Lack of control of the control factors.
 - Variation of the uncontrolled factors.



Robust Design

6

Robust Design Concepts



Concept: Choose levels of the control¹ factors in a way that reduces output variation. In other words, make the product, process or system robust to variation in the inputs; both control and uncontrolled² factors. Quality is then improved without removing the cause of variation.

1. **Control factors (x)** are parameters whose nominal values can be cost-effectively adjusted by the engineer.

Example: oven temperature.

2. **Uncontrolled factors (z)** are parameters that are difficult, expensive, or impossible to control.

Example: ambient temperature.

Robust Design

7

Control vs Uncontrolled Factors



Determining whether a factor is an uncontrolled or a controlled one often depends on the team's objective or the scope of the project. A factor considered controlled in some cases might be considered uncontrolled in others.

For example, material durometer (hardness):

- is controllable to a design engineer, who gets to choose the material.
- but may be uncontrolled to a process engineer who only sees the variation within the chosen material.


Robust Design

8

Agenda Transition



- Robust Design Concepts
- **Propagation of Error (POE)**
- RSM Analysis with TA
 - Lathe Machined Parts
 - Tolerance analysis
 - Partitioning variation to inputs




Robust Design

9

Propagation of Error (POE) Transmitted Variation



Objective: Reduce the variation transmitted to the response from variation in control factors.



Robust Design

10

Propagation of Error How it works



Once a relationship has been established between a factor and a response, the **variation** in the output can be:

1. **Dependent** on the level of the control factor
2. **Independent** of the level of the control factor

See pictures on next two pages →

Robust Design


11

Propagation of error Dependent



The transmitted variation is **dependent** on the level of the control factor.

Therefore, set the level of the control factor to reduce variation transmitted to the response from variation (lack-of-control) of the control factor.



Robust Design


12

Propagation of error Independent



The transmitted variation is **independent** of the level of the control factor.

Therefore, set the level of the control factor to center the process mean on target.



Robust Design

13


Power Circuit Design Example



Consider two control factors:

1. Transistor Gain – **nonlinear** relationship to output voltage
2. Resistance – **linear** relationship to output voltage


The variation in gain and resistance about their nominal values is known. Both variances are constant over the range of nominal values being considered.



Robust Design

14

Power Circuit Design Example (reduce variation)




Variation is reduced by using a nominal gain of 350.
That shifts the output off-target to 125 volts.

Robust Design

15

Power Circuit Design Example (return to target)



Decrease the nominal resistance from 500 to 250.
This corrects the output to the targeted 115 volts.

Robust Design


16

Power Circuit Design Example on target with reduced variation



To illustrate the theory, the control factors were used in two steps:
first to decrease variation and
second to move back on target.

In practice, numerical optimization
can be used to simultaneously
obtain all the goals.



Robust Design

17


Propagation of error Just a little mathematical explanation



Find regions where variation in the control factors transmits the least variation
to the response.

$$\hat{Y} = \beta_0 + \beta_1 x_1 + \beta_{11} x_1^2$$

$$\hat{Y} = 15 + 25x_1 - 0.7x_1^2$$



The goal is to minimize the slope, which is the 1st
derivative of the prediction equation.

Robust Design

18

Propagation of error

Just a brief mathematical explanation




$$\hat{Y} = \beta_0 + \beta_1 x_1 + \beta_{11} x_1^2$$

$$\hat{Y} = 15 + 25x_1 - 0.7x_1^2$$

$$\sigma_{\hat{Y}}^2 = \left(\frac{\partial Y}{\partial X} \right)^2 \sigma_x^2 + \sigma_{resid}^2$$

$$\sigma_{\hat{Y}} = \sqrt{(25 - 1.4x_1)^2 \sigma_x^2 + \sigma_{resid}^2}$$



As the **slope** of the relationship between X and Y decreases, the variation transmitted to Y decreases.

Robust Design

19

Propagation of error

Goal: Minimize propagated error (POE)



What is POE?

$$\sigma_{\hat{Y}}^2 = \sum_i \left(\frac{\partial f}{\partial x_i} \right)^2 \sigma_{x_i}^2 + \sum_j \left(\frac{\partial f}{\partial z_j} \right)^2 \sigma_{z_j}^2 + \sigma_{resid}^2 \quad POE = \sqrt{\sigma_{\hat{Y}}^2}$$

The amount of variation transmitted to the response
(using the transfer function):

- from the lack of control of the control factors and variability from uncontrolled factors
(you enter these standard deviations),
- plus the normal process variation
(obtained from the ANOVA).

It is expressed as a standard deviation.

Robust Design

20

Propagation of error Simple One-Factor Illustration (page 1 of 4)



One Factor RSM design.

- Factor A: low level = **0** and high level = **15**
- Design for a **cubic** model.
- Sort by Factor A**

Select	Std	Run	Factor 1 A:A	Response 1 R1
2		7	0.00	14
	1	8	0.00	16
	3	1	2.50	73
	4	6	5.00	123
	9	3	7.50	162
	10	9	7.50	164
	5	2	10.00	195
	6	5	12.50	218
	7	4	15.00	233
	8	10	15.00	231

(continued on next page)

Propagation of error Simple One-Factor Illustration (page 2 of 4)



5. Compute effects and select appropriate model.

Fitted equation (in terms of actual factor values) is:

$$\hat{Y} = 14.98 + 25.05A - 0.71A^2$$

6. Enter the standard deviation for each factor:


From the Design Layout Screen - **View, Column Info Sheet** – enter **1.00** for Factor A.

The response standard deviation is filled in automatically from the ANOVA after the analysis is completed.


Propagation of error Simple One-Factor Illustration (page 3 of 4)



Analyze the response (R1) and look at the one factor plot and the propagation of error plot (from the View menu.)



$$\hat{y} = 14.98 + 25x_1 - 0.7x_1^2$$



$$\sigma_y = \sqrt{(25 - 1.4x_1)^2 \sigma_x^2 + \sigma_{resid}^2}$$

assume $\sigma_x = 1$ and $\sigma_{resid} = 0.95$


Robust Design

23

Propagation of error Simple One-Factor Illustration (page 4 of 4)



Point Prediction node:



$$\begin{aligned} \sigma_y &= \sqrt{(25 - 1.4x_1)^2 \sigma_x^2 + \sigma_{resid}^2} \\ &= \sqrt{(25 - 1.4(7.5))^2 (1)^2 + (0.95)^2} \\ &= 14.54 \end{aligned}$$

Robust Design

24


Propagation of error Linear relationship (page 1 of 3)



If the response is a **linear function** of the independent factors, the transmitted variation is a **constant**.

$$\hat{y} = \beta_0 + \beta_1 x_1$$

$$\hat{y} = 15 + 25x_1$$



Robust Design

25

Propagation of error Linear relationship (page 2 of 3)




$$\hat{y} = \beta_0 + \beta_1 x_1$$

$$\hat{y} = 15 + 25x_1$$

$$\sigma_{\hat{y}}^2 = \left(\frac{\partial Y}{\partial X}\right)^2 \sigma_x^2 + \sigma_{resid}^2$$

$$\sigma_{\hat{y}} = \sqrt{(25)^2 \sigma_x^2 + \sigma_{resid}^2} = \text{Constant}$$

assume $\sigma_x = 1$ and $\sigma_{resid} = 3.17$



Since the slope of the relationship between X and Y is constant, the variation transmitted to the response also remains constant.

Robust Design

26

Propagation of error Linear relationship (page 3 of 3)



Point Prediction node:

The screenshot shows the Minitab Point Prediction node interface. A yellow callout box contains the following formula:

$$\sigma_y = \sqrt{(25)^2 \sigma_x^2 + \sigma_{resid}^2}$$

$$= \sqrt{(25)^2 (1)^2 + (3.17324)^2}$$

$$= 25.206$$

The callout box also includes a note: "With and without adjustment for variation in the factors and adjusted for variation in the factors and used in adjustment".


Robust Design

27

Agenda Transition



- Robust Design Concepts
- Propagation of Error (POE)
- **RSM Analysis with TA**
 - **Lathe Machined Parts**
 - Tolerance analysis
 - Partitioning variation to inputs



Robust Design

28

Robust RSM Simulation Precise Machined Parts



Acme precision machine company has been having trouble holding nominal values on their new highly-automated lathe. Your job is to study the process and reduce deviations from nominal. Previous work has determined that three factors are the key influencers on the process:

Factor	Units	Range
Cutting Speed	fpm	330 - 700
Feed Rate	ipr	0.01 – 0.022
Depth of cut	inches	0.05 – 0.10



The factor levels given are the extreme values, do not exceed them.

Robust Design


29

Robust RSM Simulation Precise Machined Parts



Which design is an appropriate choice for the Lathe DOE?

What model should we design for?



Robust Design

30

Robust RSM Simulation Precise Machined Parts



The experimenters chose to run a Box-Behnken design.

- The significant factors are already known, and optimization is the focus.
- The region of interest and the region of operability are very similar (can't exceed the stated factor levels.)
- They would like to fit a quadratic model.

The key response is delta, i.e., the deviation of the finished part's dimension from its nominal value. Delta is measured in mils, 1 mil = 0.001 inches.



Robust Design

31

Robust RSM Simulation Precise Machined Parts




1. Open the three factor Box-Behnken response surface design: "**Lathe.dxp**".
2. Fit an appropriate model (reduce as needed) to the response: delta.
3. Examine the response surface to find factor levels where delta is zero.



Robust Design

32

Robust RSM Simulation Precise Parts



Note the variety of speed and feed combinations that can produce a delta of 0.

You could also explore the other graph combinations of speed vs. depth and feed vs. depth.


Robust Design

33

Agenda Transition



- Robust Design Concepts
- Propagation of Error (POE)
- RSM Analysis with TA
 - **Lathe Machined Parts**
 - **Tolerance analysis**
 - Partitioning variation to inputs



Robust Design

34

Robust RSM Simulation Precise Parts – Add POE



1. Enter information on the expected variation of the controllable factors about their set points. From the Design node, go to “**Column Info Sheet**” and enter:


Variable	Standard Deviation
A – Speed	5 fpm
B – Feed	0.00175 ipr
C – Depth	0.0125 inches

2. Use the POE model graphs to explore the transmitted error as a function of the independent factors.

Robust Design

35

Robust RSM Simulation Precise Parts – Add POE



These are two of the three views of the propagated error
- - where is POE minimized?

Robust Design

36

Robust RSM Simulation Precise Parts – Optimization



1. Use numerical optimization to find factor levels near zero delta that are also robust:

Goal	Cpk			
	LSL	USL	Cpk Low	Cpk High
Limits:	-0.4	0.4	0	1.5
Weights:	1	1		

2. Choose settings to operate the lathe:

Speed	517 Fpm
Feed	0.022 ipr
Depth	0.065 inches
Delta	8.1E-08 mils
POE(Delta)	0.12 mils

Since the resulting C_{pk} of **1.11** is so low, we will look into partitioning the POE to see which of the sources of variation are largest.


Robust Design

37

Agenda Transition



- Robust Design Concepts
- Propagation of Error (POE)
- RSM Analysis with TA
 - **Lathe Machined Parts**
 - Tolerance analysis
 - **Partitioning variation to inputs**



Robust Design

38

Empirical Tolerancing



Predicted response:

$$\hat{y} = f(x_1, \dots, x_k) + \frac{1}{2} \sum_{i=1}^k \left(\frac{\partial^2 f}{\partial x_i^2} \right) \sigma_{ii}^2$$



POE (transmitted variation):

$$\sigma_{\hat{y}}^2 = \sum_{i=1}^k \left(\frac{\partial f}{\partial x_i} \right)^2 \sigma_{ii}^2 + \frac{1}{2} \sum_{i=1}^k \left(\frac{\partial^2 f}{\partial x_i^2} \right)^2 \sigma_{ii}^4 + \sum_{i < j} \left(\frac{\partial^2 f}{\partial x_i \partial x_j} \right)^2 \sigma_{ii}^2 \sigma_{jj}^2 + \sigma_{\text{residual}}^2$$

Residual MS:



$$\sigma_{\text{residual}}^2 = \sigma_{\text{part}}^2 + \sigma_{\text{measure}}^2 + \sigma_{\text{lack-of-fit}}^2$$

↙ 0 if not significant

Empirical Tolerancing



Residual MS: $\sigma_{\text{residual}}^2 = \sigma_{\text{part}}^2 + \sigma_{\text{measure}}^2 + \sigma_{\text{lack-of-fit}}^2$



Fit an appropriate model!

Precise Machined Parts Tolerance Analysis



Source	Sum of Squares	df	Mean Square	F Value	p-value Prob > F
Model	1.36	7	0.19	42.65	< 0.0001
A-Speed	0.037	1	0.037	8.17	0.0189
B-Feed	0.15	1	0.15	32.42	0.0003
C-Depth	0.35	1	0.35	77.80	< 0.0001
AB	0.27	1	0.27	59.70	< 0.0001
AC	0.24	1	0.24	53.21	< 0.0001
A^2	0.025	1	0.025	5.52	0.0434
C^2	0.27	1	0.27	59.53	< 0.0001
Residual	0.041	9	4.558E-003		
Lack of Fit	0.019	5	3.740E-003	0.67	0.6689
Pure Error	0.022	4	5.582E-003		
Cor Total	1.40	16			

Robust Design

41

Precise Machined Parts Partitioning Variation to Inputs *(page 1 of 2)*



At the optimal point, calculate the reduction in error variance by setting one standard deviation at a time to zero:

	A	B	C	D	E
1		s(POE)	s^2(POE)	Reduction	%
2	(s=0.67516, A=5, B=0.00175, C=0.0125)	0.11985	0.01436		
3	(s=0, A=5, B=0.00175, C=0.0125)	0.09903	0.00981	0.00456	31.7%
4	(s=0.67516, A=0, B=0.00175, C=0.0125)	0.11922	0.01421	0.00015	1.1%
5	(s=0.67516, A=5, B=0, C=0.0125)	0.11287	0.01274	0.00163	11.3%
6	(s=0.67516, A=5, B=0.00175, C=0)	0.07950	0.00632	0.00805	55.9%
7				0.01438	100.0%

See graph on next slide!

Robust Design


42

Precise Machined Parts

Partitioning Variation to Inputs (page 2 of 2)



Percent overall POE is reduced by setting each factor standard deviation to zero



Robust Design

43

Precise Machined Parts

Reducing Variation in Depth (factor C)



Name	Units	Type	Changes	Std. Dev	Low	High
Speed	fpm	Factor	Easy	5	330	700
Feed	ipr	Factor	Easy	0.00175	0.01	0.022
Depth	inches	Factor	Easy	0.00625	0.05	0.1
delta	mil	Response		0.00163	-0.394	0.572

Reduce std dev by 1/2
0.0125 → 0.00625

Increase C_{pk} Upper to 2

Robust Design

44

Precise Machined Parts Reducing Variation in Depth (factor C)



C_{pk} of 1.53 is a good improvement:

Factors						
Factor	Name	Level	Low Level	High Level	Std. Dev.	Coding
A	Speed	536.80	330.00	700.00	5.00	Actual
B	Feed	0.0220	0.0100	0.0220	0.0018	Actual
C	Depth	0.0662	0.0500	0.1000	0.0063	Actual

Point Prediction										
Two-sided Confidence = 95% Population = 99%										
Solution 1 of 20 Response	Predicted Mean	Predicted Median	Observed	Std Dev*	SE Mean	95% CI low for Mean	95% CI high for Mean	95% TI low for 99% Pop	95% TI high for 99% Pop	Cpk
delta	-0.0159013	-0.0159013		0.0675163	0.0356395	-0.0965233	0.0647208	-0.367349	0.335547	1.90
delta (POE)*	-6.03864E-08	-6.03864E-08	-	0.0869945	0.0459214	-0.103881	0.103881	-0.45284	0.45284	1.53

Can sigma for factor C be reduced to 0.00625?

Robust Design

45

Precise Machined Parts Reducing Variation in Depth (factor C)



Factor	Name	Level	Low Level	High Level	Std. Dev.	Coding
A	Speed	536.8	330.0	700.0	5.000	Actual
B	Feed	0.02200	0.01000	0.02200	0.001750	Actual
C	Depth	0.06619	0.05000	0.1000	0.006250	Actual

Solution 1 of 20 Response	Predicted Mean	Predicted Median	Std Dev*	SE Mean	95% CI low for Mean	95% CI high for Mean	95% TI low for 99% Pop	95% TI high for 99% Pop	Cpk	
delta	-0.01590	-0.01590	0.06752	0.03564	-0.09652	0.06472	-0.3673	0.3355	1.896	
delta (POE)	-6.039E-08	-6.039E-08	-	0.08699	0.04592	-0.1039	0.1039	-0.4528	0.4528	1.533

C_{pk} of 1.53 is a good improvement:

- Can sigma for factor C be reduced to 0.00625? At what cost?
- Still not six sigma, see Tolerance Intervals in relation to the specifications of -0.40 to +0.40.

Robust Design

46

References



- 1) Raymond H. Myers, Douglas C. Montgomery and Christine M. Anderson-Cook (2016), 4th edition, Response Surface Methodology, John Wiley and Sons, Inc, Sections 2.7-2.8 and 6.6, Chapters 1, 7 and 11.
- 2) George E.P. Box, William G. Hunter and J. Stuart Hunter (2005), *Statistics for Experimenters*, 2nd edition John Wiley, Chapter 13.
- 3) Steven DE Gryze, Ivan Langhans and Martina Vandebroek, "Using the Intervals for Prediction: A Tutorial on Tolerance Intervals for Ordinary Least-Squares Regression", *Chemometrics and Intelligent Laboratory Systems*, 87 (2007) 147 – 154.
- 4) Gerald J. Hahn and William Q. Meeker, *Statistical Intervals; A Guide for Practitioners*, (1991) John Wiley and Sons, Inc.

Stat-Ease Training: Sharpen Up Your DOE Skills



Modern DOE for Process Optimization Mixture Design for Optimal Formulations

Individuals	Teams (6+ people)
Improve your DOE skills	Choose your date & time
Topics applicable to both novice and advanced practitioners	Add company case studies

Learn more: www.statease.com

Contact: workshops@statease.com



StatEase
statistics made easy.
Make the most from every experiment!™

Thank You for Attending

Robust Design 49